



Orig Tree Position	Site	Original Tree Species	Confirm Reason For Removal	6 D's	Planting Notes	Original Tree Easting	Original Tree Northing	Replant Species	Replant Easting	Replant Northing
SIDE OF 53 WOSTENHOLM RD, top of Albany road by junct with Wostenholm Rd	ALBANY ROAD	<i>Tilia x europea</i>	Damage to Surface	Damaging	TR: Replanting, <i>Tilia 'Redmond'</i> - Plant in new 800 pit opposite 56 Albany Rd (same as felled tree)	434638.74	385505.79	<i>Tilia americana 'Redmond'</i>	434639.57	385504.45
O/S 56, at top Albany Rd at junct with Wostenholm	ALBANY ROAD	<i>Tilia x europea</i>	Damage to Surface	Damaging	TR: Replanting, <i>Tilia 'Redmond'</i> - Plant in new 800 pit o/s 56 Albany Rd at top of road, (same as felled tree)	434643.74	385511.89	<i>Tilia americana 'Redmond'</i>	434644.15	385511.96
O/S 45, (opp 40)	ALBANY ROAD	<i>Tilia x europea</i>	Damage to Surface	Damaging	TR: Replanting, <i>Tilia 'Redmond'</i> - Plant in new 800 pit o/s 45- opposite 40 (same as felled tree)	434686.46	385448.25	<i>Tilia americana 'Redmond'</i>	434686.75	385448.3